

Disc many gaugests to size, to

cement to joining surfaces. Allow to dry. Final application of cement must be made just before joining. Use headless pins for reinforcing. Cut notches in wings to receive motor nacelles. Cement motor cowls, exhaust pipes and air intakes, to nacelles. Any struts required can be inserted by trying for right lengths. Although we consider tentnele powdered cement preferable for this type of model, liquid cement can be taked.

STEP No. 5 \* Complete streamlining with fillets of scrap balsa or heavy tentacle cement. Round and smooth with sandpaper.